

(SUBMIT IN TRIPLICATE)


Land Office Las Cruces

Lease No. 065525

Unit _____

DUPLICATE

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 4, 1951, 19____

Well No. 1 is located 660 ft. from S line and 660 ft. from W line of sec. 1

SW 1/4, Sec. 1 (1/4 Sec. and Sec. No.) T-21-S (Twp.) R-37-E (Range) N.M.P.M. (Meridian)
Wildcat (Field) Leas (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

13-3/8" 48# H-40 casing was set @ 238' and cemented with 250 sacks on September 4, 1951. We let cement set for 2 1/2 hours, applied 1000# pressure let set for one hour, no drop in pressure was noted, cement was found at 207'. Drilled plug and 1' below. Applied 600# to casing let set for 1 hour final pressure 520#. Drilling was resumed.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Fullerton Oil Company

Address P.O. Box H

Hobbs, New Mexico

By L. W. Ferrigan
Title Office Manager