:			
Form 3160-5 (June 1990)	Νô	116	

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

5. Lease Designation and Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS

NMLC065525A

Do not use this	form for proposals to dr	ill or to deepen or reentry to a different reservoir. R PERMIT—" for such proposals	6. If Indian, Allottee of Tribe Name		
	SUBMIT	7. If Unit or CA, Agreement Designation			
1. Type of Well Oil Well Gas Well	Other		8. Well Name and No.		
2. Name of Operator			Elliott Federal #2		
John H. Hendrix Corporation			30-025-063300SI		
3. Address and Telephone No. P. O. Box 3040, Midland, TX 79702-3040		10. Field and Pool, or Exploratory Area			
	age, Sec., T., R., M., or Survey D		Drinkard		
			11. County or Parish, State		
1980' FSL	& 1980' FWL Se	ec. 1, T21S-R37E	Lea County, NM		
12. CHECK	APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPOI	RT, OR OTHER DATA		
TYPE OF	SUBMISSION	TYPE OF ACTION			
Notice	of Intent	Abandonment	Change of Plans		
	Of Allein	Recompletion	New Construction		
Subsequent Report		Plugging Back	Non-Routine Fracturing		
••		Casing Repair	Water Shut-Off		
Final Abandonment Notice		Altering Casing	Conversion to Injection		
		Other	Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)		
13. Describe Proposed or C give subsurface lo	Completed Operations (Clearly state a ocations and measured and true verti	Il pertinent details, and give pertinent dates, including estimated date of startin cal depths for all markers and zones pertinent to this work.)*	g any proposed work. If well is directionally drilled,		
1/29/96			ted P&A mud fr.		
7 /20 /06	5675' to 3200'. Spotted 25 sx. Class "C" cement plug fr. 5675 - 5457'. Cut csg. at				
1/30/96	1/30/96 Spotted 25 sx. Class "C" cement plug fr. 5675 - 5457. Cut csg. a 3189' & recovered 3180' of 5-1/2" csg. Spotted 90 sx. Class "C"				
	fr. 3250' to 2	2779'.	-1		
1/31/96	2828' to surface	tagged cement plug at 2828'. (ce. Spotted 30 sx. cement plug-hole marker. Cleaned location Caffey.	fr. 120' to surface.		

Approved us to plugging of the wall time.
Liability under bond is retained units
surface restoration in completed.

14. I hereby cerulfy what the foregoing is true and correct Signed	Title	Vice-President	Date 3/13/96
(This space for Federal or State office use) Approved by Oriz Signed by Shannon J. Shaw	Title	PETROLEUM ENGINEER	Date 4/12/96
Approved by			Jane