

DUPLICATE

OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

RECEIVED
APR 23 1948
HOBBS OFFICE

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of report by checking below.

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL		REPORT ON PULLING OR OTHERWISE ALTERING CASING	
REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON DEEPENING WELL	
REPORT ON RESULT OF PLUGGING OF WELL	X		

April 19, 1948

Hobbs, New Mexico

Date

Place

OIL CONSERVATION COMMISSION,
SANTA FE, NEW MEXICO.

Gentlemen:

Following is a report on the work done and the results obtained under the heading noted above at the _____

Stanolind Oil and Gas Company Southland Royalty A Well No. 3 in the _____

Company or Operator

Lease

3 1/4

of Sec. 2

T. 21

R. 37

N. M. P. M.,

Drinkard

Field,

Lea

County.

April 17, 1948

The dates of this work were as follows: _____

Notice of intention to do the work was (~~was not~~) submitted on Form C-102 on April 17 1948and approval of the proposed plan was (~~was not~~) obtained. (Cross out incorrect words.)

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

On April 17, 1948, the well was conditioned with 10# mud and a 30 sack cement plug was placed from 6630 to 6730 to shut off bottom water. The hole was then filled to 2550 with 10# mud and a 30 sack cement plug placed from 2500 to 2550 at the base of the salt. The hole was filled to 1385 with 10# mud and a 10 sack cement plug placed from 1365 to 1385 at the base of the 10-3/4" surface string. The hole was then filled to within 30' of the surface and a 10 sack cement plug placed to within 3' of the top of the 10-3/4" and a 4' marker was erected.

Witnessed by Tom Holden Stanolind Oil and Gas Co. Head Roustabout
Name Company Title

Subscribed and sworn before me this 21st

I hereby swear or affirm that the information given above is true and correct.

day of

April

1948

Name

Lester Henderson

Position

Field Supt.

Notary Public

Representing Stanolind Oil and Gas Co.
Company or Operator

My commission expires 2-23-50

Address Box F; Hobbs, New Mexico

Remarks:

APPROVED

Date APR 22 1948

Ray J. Henderson
Name
Title