

X			

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **Las Cruces**
Lease No. **LC 031741 b**
Unit **NMFU**

RECEIVED OCT 31 1956

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	X	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Blank B-3

October 30, 1956

Well No. **3-7B** is located **660** ft. from **(N)** line and **1980** ft. from **(E)** line of sec. **3**
NW/4 Sec 3 **21 S 37 E** **R17N**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Terry Blinbry **Lea** **New Mexico**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Our Notice of Intention to Drill the above well, approved 10-17-56, indicated an estimated TD of 6450' and a completion in the Tubb formation. A TD of 6480' was reached, and the Tubb found to be unproductive. It is intended to plug back to 6300', and complete this well in the Terry Blinbry Pool.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.


Company **Continental Oil Company**

Address **Box 68**

Lunice, New Mexico

By _____

Title **District Superintendent**



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYLand Office **Las Cruces**
Lease No. **LC 031741 b**
Unit **NMPU**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Hank B-3

October 24, 1956

Well No. **3-TB** is located **660** ft. from **N** line and **1980** ft. from **W** line of sec. **3****N 1/4 Sec 3**

(1/4 Sec. and Sec. No.)

21 S 37 E

(Twp.)

(Range)

NMPM

(Meridian)

Terry Blinbry

(Field)

Lea

(County or Subdivision)

New Mexico

(State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Ran 198 joints 5 1/2" casing set at 6479' with 500 sacks, plug down 10-18-56. Top of cement 2903'. Tested casing with 1000' for 30 minutes before and 650' for 30 minutes after drilling plug. Tested OK.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Continental Oil Company**Address **Box 68, Sunice, New Mexico**

By _____

Title **District Superintendent**