



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Cruces
Lease No. 031741 (b)
Unit 10FU

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	Subsequent report of cleanout and sandfrac.....

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Blank P-10

March 17, 1959

Well No. 4-7 is located 990 ft. from N line and 910 ft. from W line of sec. 10
1/4 Sec. 10 21-3 37-3 100N
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Barro Lea New Mexico
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3464 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

BETTER WORKOVER - TD 8090' sand, TB 8044', OF 11', elev. 3444' BP. Pay McKee 7637-7816'. Casing 5 1/2" at 8089'. Perfs. 7637-92', 7702-59', 7780-7816'. TD oil well prior to workover.

MORE WORK - Cleaned out to 8044'. Sandfraced McKee 7637-7816' w/12,000 gallon standard treatment. Installed 21 flow valves. Recovered lead oil.

AFTER WORKOVER - TD 8090' sand, TB 8044'. Pay McKee 7637-7816'. Perfs. 7637-92', 7702-59', 7780-7816'. IF gas lifted 95 MC, 5 MC, in 24 hrs, thru 3/4" chx. TP 75 lbs., CP 500 lbs, w/166 HRTS. 302 1747. OGR 95 Hbls. Daily allow. 80 MC. Workover started 2-28-59, completed 3-6-59. Well tested 3-14-59.

I understand that this plan of work must receive approval in writing

Company Continental Oil Company

Address P.O. Box 68

El Paso, New Mexico

ILLEGIBLE

By _____

Title District Superintendent