

DUPLICATE

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office

Las Cruces

Lease No.

032096-0

Unit

N.M.P.M.

RECEIVED
JUL 30 1951
OIL CONSERVATION COMMISSION
HOBBS OFFICE

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

A. M. Lockhart B-11 No. 2-D

Hobbs, New Mexico

July 26, 1951

Well No. **2-D** is located **330** ft. from **N** line and **330** ft. from **W** line of sec. **11**

11/4 Sec. 11
(1/4 Sec. and Sec. No.)

21-3
(Twp.)

37-E
(Range)

N.M.P.M.
(Meridian)

North Drinkard
(Field)

Lea

(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Set 10 3/4" casing at 266' with 250 sacks cement. Cement was circulated to surface. Plug down 12:00 Noon, 7-17-51.

On 7-18-51, after 24 hrs. WOC, tested casing with 250# for 30 minutes before drilling plug, final pressure 24.5#. Drilled out plug and tested casing with 250# for 30 minutes, final pressure 24.0#.

ILLEGIBLE

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Continental Oil Company**

Address **Box CC**

Hobbs, New Mexico

By

Title **District Superintendent**

035050-8
U.S.A.

I

II 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

of bearing to use (cases) (cases) use of material to
surface. (down 1000 ft) (down 1000 ft) (down 1000 ft)
on 1-10-52, after 25 hrs. 200, tested casing with 200 for 30 minutes before
drilling pipe, then pressure 200. (down 1000 ft) (down 1000 ft) (down 1000 ft)
for 30 minutes, then pressure 200.

Continued 100 (down 1000 ft)
100 (down 1000 ft)
100 (down 1000 ft)

Continued 100 (down 1000 ft)