

DISTRIBUTION			
OFFICE			
OR			

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name STATE SEC. 2
9. Well No. 16
10. Field and Pool, or Wildcat DRINKARD/BLINEBRY
12. County LEA

SUNDRY NOTICES AND REPORTS ON WELLS DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.

WELL ☒ GAS WELL ☐ OTHER ☐

Name of Operator
SHELL OIL COMPANY

3. Address of Operator
P. O. BOX 991, HOUSTON, TEXAS 77001

4. Location of Well
UNIT LETTER K 3546 FEET FROM THE North LINE AND 1700 FEET FROM
THE West LINE, SECTION 2 TOWNSHIP 21S RANGE 37E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)
3502 DF

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER Completion of DHC of Drinkard/Blinebry ☒

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7/16/79 Knocked out CIBP above Drinkard @ 6550'. Reperfed existing Drinkard original perms.
thru 6641'-6704' & perf'd lower Drinkard interval 6783'-6932' (32 shots). Attempted to
7/25/79: acidize lower Drinkard interval 6783'-6932'. Could not break down Drinkard. Reperf'd
entire Drinkard interval 6641'-6932'. Attempted to acidize lower Drinkard. Communi-
cated with upper Drinkard perms. Packer stuck @ 6750'. Cut off tubing @ 6746'. Acid
treated 6641'-6704' w/4,000 gals 15% NEA. Frac treated 6641'-6704' w/17,000 gals
frac containing 2#/gal 20-40 mesh sand. (Job incomplete due to packer failure.)

8/06/79: Ran 2 7/8" tubing & hung @ 6668'. Placed well on pump.

18. I hereby certify that the information above is true and complete to the best of my knowledge

SIGNED A. J. Fore

TITLE A. J. Fore
Sr. Engineering Tech.

10/31/79

APPROVED BY John Runyan
Geologist

TITLE _____

DATE NOV 6 1979