



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Cruces

Lease No. 1C 031741 (b)

Unit WPU

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			
Subsequent Report of Perf. Additional Zones & Acidize			<u>X</u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Hawk B-3

December 8, 1958

Well No. 4 is located 1650 ft. from LINE line and 1650 ft. from W line of sec. 3

SE 1/4 Sec. 3

(1/4 Sec. and Sec. No.)

21 S

(Twp.)

37 E

(Range)

WPM

(Meridian)

Brunson

(Field)

Lee

(County or Subdivision)

New Mexico

(State or Territory)

The elevation of the derrick floor above sea level is 3435 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

BEFORE WORKOVER - TD 8070' Dolo., DF 10', Elev. 3435' DF. Pay Ellenburger 8014-8038'. Csg. Pt. 5 1/2" at 8069'. Perfs. 8014-8038'. Pumped 8 BO, 7 Bx, in 24 Hrs. w/2.17 MCPOPD. GOR 271. Daily oil rate 8 Bbls. Daily allowable 3 BO.

WORK DONE - Ran PFC Log. Perf. 7948-64' and 7967-8003' w/4 shots per foot. Acidized w/15,000 gallons acid.

AFTER WORKOVER - TD 8070' Dolo. DF, Elev., same as before workover. Pay Ellenburger 7948-8038'. Perfs. 7948-64', 7967-8003', 8014-8038'. IF pumped 8 BO, 23 Bx, in 24 Hrs. w/9.38 MCPOPD. GOR 1172. Daily oil rate 8 Bbls. Daily allowable 8 BO. Workover started 11-3-58, completed 11-11-58. Well tested 11-29-58. Workover did not result in increased production.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Continental Oil Company

Address Box 68

Donna, New Mexico

By _____

Title District Superintendent