


(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

W. O. Rank 8-3 No. 2-3

Hobbs, New Mexico October 9, 1951

Well No. 1-9 is located 810 ft. from [N] line and 460 ft. from [E] line of sec. 9

Sec. 1 (1/4 Sec. and Sec. No.) Twp. 36 N Range 30 E Meridian 14 N  
Hildred (Field) Jax (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 3653 ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Set 3 1/2" casing at 7025' with 52# sands cement. Plug down at 6:35 A.M., 9-11-51. Top of cement by compressive survey 3230'.

Moved in reverse rig and on 10-6-51, after 48 hours WOC, tested casing with 2,000#, dropped to 775#. Drilled out cement and tested casing with 2,000# for 30 minutes. Final pressure 960#.

ILLEGIBLE

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Continental Oil Company

Address Hobbs, New Mexico

By

Title District Engineer