


(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Alamos

Lease No. 031711



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

U. C. Hook No. 1-3

Hobbs, New Mexico October 8, 19 51

Well No. 2-8 is located 810 ft. from N 1/4 line and 660 ft. from E 1/4 line of sec. 3

SE 1/4 Sec. 3

(1/4 Sec. and Sec. No.)

21-S

(Twp.)

37-E

(Range)

N. V. P. M.

(Meridian)

Mildred

(Field)

Los

(County or Subdivision)

New Mexico

(State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

Set 7 5/8" casing at 3149' with 1420 sacks cement. Plug down 6:00 A.M. 8-29-51.
Top of cement by temperature survey 575'.

On 8-31-51, after 48 hrs. POC, tested casing with 1000# for 30 mins., test okay. Drilled out cement and tested casing with 1000# for 30 mins., 25# pressure drop.

ILLEGIBLE

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Continental Oil Company

Address Box 427, Hobbs, New Mexico

By [Signature]
Asst.

Title District Superintendent