



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-R358.4
Approval expires 12-31-60.

Land Office Las Cruces
Lease No. 032096 (b)
Unit G

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	☒
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

April 26, 1962

Lockhart 3-11
Well No. 17

is located 1980 ft. from N line and 1980 ft. from E line of sec. 11

N2/4 Sec 11
(1/4 Sec. and Sec. No.)

21S
(Twp.)

37E
(Range)

NMPM
(Meridian)

New Mexico
(State or Territory)

Wanta, Bob & Drinkard
(Field)

Lea
(County or Subdivision)

The elevation of the derrick floor above sea level is 3455 ft. MB

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Set 3102' of 36" J-55 9 5/8" OD casing at 3094' w/1150 sx cement.
ROC 36 hours. Top of cement at 1600' by temperature survey.
Thirty minute casing test before and after plug was drilled - 1000%.
Tested O. K.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Continental Oil Company

Address Box 68

Lunice, New Mexico

0/2 USGS 100-2-244 file

By J. K. R. [Signature]

Title District Superintendent