Submit this report in triplicate to the Oil Conservation Commission District Office within ten days after the work specified is completed. It should be signed and filed as a report on beginning drilling operations, results of shooting well, results of test of casing shut off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

	Indicate n	ature of repo	rt by checking belo	w.		
REPORT ON BEGINNING DRILLING OPERATIONS			REPORT ON REPAIRING WELL			
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL			REPORT ON PULLING OR OTHERWISE ALTERING CASING			E
REPORT ON RESULT OF TEST OF CASING SHUT-OFF			REPORT ON DEEPENING WELL			
REPORT ON RESULT OF PLUGO	ING OF WELL	C				
		Be	sember 17, 195	61 H	obbs. New	Mexico
			Date		Pla	ice
Following is a report on the work d						
Shell Company or Operator			Argo Lease	Well No	12	in the
S company or of	of Sec	15	, T 21-S	, R	37-E	, N. M. P. M.,
Hare	Pool	Lea				County.
The dates of this work were as follo	ows: Dec	ember 15.	1951		-,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
·	200 AM 12-1		OONE AND RESUL	IS OBTAIN.	BD	
Witnessed by	vehouse		Shell Oil Co	apany	Production	on Poreman
APPROVED: OIL CONSERVATION COMMISSION Name Title			I hereby swear or affirm that the information given above is true and correct. Name L. E. Slagle L. L. L. Position Division Mechanical Engineer Representing Shell Oil Company			
NEO 1	<u> 1951 </u>	., 19	Representing	Compa	ny or Operator	New Mexico