

FORBES OFFICE 016

PACKER LEAKAGE TEST

OPERATOR Sunray Mid-Continent Oil Company, Box 128, Hobbs, New Mexico

LEASE NAME State Land #15#

WELL NO. 3

LOCATION Unit 0 Sec. 16 T21S R 37E

COUNTY Lea

TEST DATA SHEET

Blinebry Oil Drinkard

<u>Time</u>	<u>Casing Pressure</u>	<u>Tubing Pressure</u>	<u>Remarks</u>
<u>P.M. 10-27-58</u>	<u>900#</u>	<u>100#</u>	<u>Drinkard zone shut in</u>
<u>P.M. 10-28-58</u>	<u>900#</u>	<u>850#</u>	<u>Blinebry zone shut in</u>
<u>P.M. 10-29-58</u>	<u>1440#</u>	<u>1000#</u>	<u>Started blow down Blinebry zone</u>
<u>P.M. 10-30-58</u>	<u>100#</u>	<u>1100#</u>	<u>Blow down Blinebry zone completed.</u>
<u>P.M. 10-30-58</u>	<u>100#</u>	<u>1100#</u>	<u>Blinebry zone shut in, Drinkard zone opened by mistake</u>
<u>A.M. 10-31-58</u>	<u>1250#</u>	<u>25#</u>	<u>Drinkard zone shut in</u>
<u>A.M. 11-1-58</u>	<u>1460#</u>	<u>1100#</u>	<u>Drinkard zone opened for blow down</u>
<u>A.M. 11-2-58</u>	<u>1500#</u>	<u>0#</u>	<u>Blow down Drinkard zone complete</u>

Checked Recorder with DWT as follows:

[illegible]