

#### (SUBMIT IN TRIPLICATE)

## DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

Land Office	Las Cruces
Lease No	32096 (a)

SUNDRY NOTICES AND REPORTS ON WELLSUG 27 1951					
NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF SHOOTING OR CIDIZING HOBS-OFFICE SUBSEQUENT REPORT OF REDRILLING OR REPAIR SUBSEQUENT REPORT OF ABANDONMENT SUBSEQUENT REPORT OF ABANDONMENT SUPPLEMENTARY WELL HISTORY.				

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

		***************************************	August 24,	, 19
Well No. A. H. LOTHING	ocated 2320 ft. f	$\operatorname{rom}\left\{ egin{array}{c} \ S \end{array} \right\}$ line as	and $\underbrace{990}_{\text{ft. from}} \left\{ \begin{array}{c} \mathbf{E} \\ \mathbf{W} \end{array} \right\}$ line of $\mathbf{S}$	sec <b>17</b>
(% Sec. and Sec. No.)	(Twp.)	(Range)	(Meridian)	
(Field)	(Coun	ty or Subdivision)	(State or Territory)	

The elevation of the derrick floor above sea level is \_\_\_\_\_\_ft.

#### **DETAILS OF WORK**

ected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cement-ing points, and all other important proposed work)

### Acidined August 22, 1951

The total depth was 6650's 52" easing comented 86600' and a Reckmill packer was not 86609-20". We adding this well under the packer with 7500 gallens section Acid. One well had previous that twice with 1000 and 1,000 gallons respectively.

# ILLEGIBLE

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.		
Company	Distlys Drilling Cospess	
Address	Den 3027, Change, Torres	1
***************************************	**************************************	By Morany
	***************************************	Title Title

No. 2 Contract Contra 322 . . . . .