NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, result of plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

	Indicate Nature of Repor	t by Checking Below		
REPORT ON BEGINNING DRILLING OPERATIONS	REPORT ON RESULT OF CASING SHUT-O	T OF TEST X	REPORT ON REPAIRING WELL	
REPORT ON RESULT OF PLUGGING WELL	REPORT ON RECOM OPERATION	IPLETION	REPORT ON (Other)	
	April 8,	, 1953	Fort Worth, Texas	ace)
Following is a report on the	ne work done and the results obtained u	ander the heading note	d above at the	
Neville G.	Penrose, Inc.		Alves (Lease)	
· •	ey or Operator) Sontractor)	Well No	•	of Sec. 18 ,
	M., Penrose Skelly			
The Desce of this work were as f	olows: Casing shut-off 4/7/53	}		
Notice of intention to do the wo	ork (was) (was not) submitted on Form ((Cr	oss out incorrect words)	
and approval of the proposed pl	an (was) (was not) obtained.			
	` ' `			
	DETAILED ACCOUNT OF WORK D	ONE AND RESULT	S OBTAINED	
7" OD casin Rotary thois drilled April	g was set at 3731 and comente moved off and completion rig (7, 1953.	ed with 80 sacks of moved in. Plug	of cement on April 2, 1 tested OK and was	
7" OD casin Rotary tools drilled April	perailed account of work by was set at 3731 and cemente moved off and completion rig (17, 1953.	rille G. Penrose,	inc. Vice Presi	
7" OD casin Rotary thois drilled April	g was set at 3731 and comente moved off and completion rig (7, 1953.	ed with 80 sacks of moved in. Plug	of cement on April 2, 1 tested OK and was	