

JOHN H. HENDRIX, CORPORATION

LEASE & WELL Elliot A #3 WELL STATUS Plug + Abandon
 JOB DESCRIPTION P+A - API Well #30-025-0671800 ST, S.N. - Lease # NMLC032591A
 GHH SUPERVISOR TBCARRUTH .. CONTRACTOR ELWS #17
 TD/PBD 7845/Surface TBG. SIZE 2 3/8 O.H. None
 CSG. SIZE 5 1/2", 9 5/8", 13 3/8" PERFS N/A -
 FORMATION Blinberry S.N. @ N/A

DATE:	DESCRIPTION OF WORK
1-30-95	Notified Vince w/ BLM @ 1:20 P.M. 1-30-95 of Plans to Start P+A Operations.
1-31-95	MIRU Eunice Well Service Rig #17.
2-1-95	N.D. Well head Equip., N.U. BOP. Work stuck Tbg. Free. - R.U. HOWCO + Attempt to break circ. - Press. to 2000 psi - Tbg. was Plugged. - SLMOH w/ 187 Its 2 3/8, 4.7* J-55, 8.0 EUE Tbg., S.N. Pert. Sub w/ Bull Plug on bottom. - Bottom 3 Its. Plugged w/ Iron Sulfide + Scale. - SLM = 5782'. - R1H w/ 2 3/8" Mule Shod Tbg. Sub, S.N., + 157 Its 2 3/8" Prod. Tbg. - Tag Top of Parted Csg. @ 4860'. - Work End of Tbg. down to 5189' - Could go no deeper. - Repeat Attempt to get in to top of Csg. + go deeper, but w/ no success. POH w/ Tbg. + Mule Shod Sub - Found cmt. on bottom of shoe. - Talked w/ Steve Caffey w/ BLM of Well bore Conditions.
2-2-95	R1H w/ 2 3/8" Bent Sub w/ Mule Shod bottom on 2 3/8" Prod. Tbg. Work thru bad Csg. from 4696' to 5096' - Was Unable to go deeper. - Discussed situation w/ Steve Caffey w/ BLM,

Cont. B. #2