

HUNT ENERGY CORPORATION

406 N. BIG SPRING
MIDLAND, TEXAS 79701

MARCH 17, 1983


Melba Carpenter
State Of New Mexico
Energy & Minerals Department
Oil Conservation Division
P.O. Box 1980
Hobbs, New Mexico 88240

Dear Ms. Carpenter,

I can understand your confusion as to why the packer was left in the well on our Mittie Weatherly #3. I have attached a wellbore diagram which should help you in understanding our present production string hookup on this well. Basically, the only reason the pkr. was installed was to allow us to easily isolate either zone downhole for testing purposes.

I hope this will answer all of your questions. Thank you for your patience.

Sincerely,



Earl W. Levea
District Engineer

Enclosure

EWL/rh