NO. OF COMES PECLIVED			Form C-101 Supersedes Old
DISTRIBUTION			C-102 and C-103
SANTA FE	NEW MEXICO OIL CONSERY	ATION COMMISSION	Effective 1-1-65
rn.c	_		
U.S.G.S.	_		State State Fee X
LAND OFFICE	_		
OPERATOR	J		5. State Off & Gas Leage No.
			- HILLER STREET
LOO HOT USE THIS FORM FOR A	RY NOTICES AND REPORTS ON WEL ACCURACY TO MAKE TO MAKE THE WARREST ATTON FOR PERMIT AN INCOME CALOUTERS CONTRIBUTED	D A DIFFERENT RESERVOIR.	7. Unit Agreement Marie
OIL X SAS WILL	отнек-		6, Farm or Lease Name
N. B. Hunt			Weatherly
. Address of Operator 1021 Western United L	ife Building Midland, Texas	79701	9. Well No. 6
. Lecution of Well	980 FEET FROM THE North		10. Field and Pool, or Wildeat Eunice Blinebry Oil
•			1 thing him are this
THE East LINE, SECT	10N 21 TOWNSHIP 21-S		
	15. Elevation (Show whether DF, R 3466 DF	T. GR, etc.)	12. County Lea
	Appropriate Box To Indicate Natura	•	her Data T REPORT OF:
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		• • • • • • • • • • • • • • • • • • • •	
PERFORM REMEDIAL WORK	PLUG AND ABANDON REM	EDIAL WORK	ALTERING CASING
TEMPORARILY ABAHOON	Срм	MERCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASI	NG TEST AND CEMENT JOB	· —
	۰	THER	
OTHER			
A packer leakage The dual strings of the between the two packers	test indicated communication j. were pulled 7-5-77. Severa and were suspected to be the uipment was replaced as before	between the Blinebry 1 badly corroded tbg. cause of the leak.	and Drinkard zones. collars were found The tbg. was tested
Model "J" packer at 547 being run now and will	'O'. Both zones were swabbed	to flowing. A packer	leakage test is
	•		
I hereby certify that the information	above in true and complete to the best of my ki	iowledge and belief.	
KED	TITLE District	t Superintendent	DAYE 7-29-77
	7171 C		DATE

ORDITIONS OF APPROVAL, IF ANYLOGICE

CIL CONSTRUMENT W. W. W.