

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103  
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company <b>Gulf Oil Corporation</b>			Address <b>Box 2167, Hobbs, New Mexico</b>			
Lease <b>Exbank</b>	Well No. <b>5</b>	Unit Letter <b>B</b>	Section <b>22</b>	Township <b>21-E</b>	Range <b>37-E</b>	
Date Work Performed <b>Apr. 20-May 4, 1959</b>	Pool <b>Paddock</b>		County <b>Lea</b>			

THIS IS A REPORT OF: (Check appropriate block)

Beginning Drilling Operations   
  Casing Test and Cement Job   
  Other (Explain): **Attempted Recompletion**  
 Plugging   
  Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

Attempted abandonment of Brunson Pool and recompletion in Paddock Pool as follows:

1. Set 7" Baker CI BP at 7403'. Dumped 2 sacks cement on top of BP.
2. Perf 7" csg 5164-74', 5186-92', 5216-22', 5235-41', 5250-60'.
3. Treated with 1000 gals 15% NE acid.
4. Radioactive tracer survey indicated gas channeling to bottom perforation at 5260' from 5320'.
5. Perf 7" csg with 4, 1/2" bullet holes at 5310'. Set CI cmt retainer at 5264'. Pumped 30 sacks sulphate resistant cement thru perfs at 5310'. Spotted 30 sacks cement from 5264-5200'. WOC.
6. Acidized perfs 5164-75' & 5186-92' with 2000 gals 15% regular acid. Tested. Acidized with 4000 gals 15% regular acid.

Did not find oil in commercial quantities. Well temporarily abandoned.

BE NOTIFIED  
 THE COMMISSION ON FORM C-103  
 EVERY 6 MONTHS ON FORM C-103  
 AS TO THE WELL STATUS AND YOUR  
 FUTURE PLANS FOR THIS WELL.

Witnessed by <b>F. G. Crawford</b>	Position <b>Field Foreman</b>	Company <b>Gulf Oil Corporation</b>
---------------------------------------	----------------------------------	--

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA

D F Elev. <b>3424' GL</b>	T D <b>7756'</b>	P B T D <b>-</b>	Producing Interval <b>7644-7756'</b>	Completion Date <b>4-14-50</b>
Tubing Diameter <b>2-3/8"</b>	Tubing Depth <b>7748'</b>	Oil String Diameter <b>7"</b>	Oil String Depth <b>7644'</b>	
Perforated Interval(s)				
Open Hole Interval <b>7644-7756'</b>			Producing Formation(s) <b>Hillenburger</b>	

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover	<b>3-13-59</b>	<b>0</b>	<b>556.0</b>	<b>0</b>	<b>-</b>	
After Workover	<b>Well TA</b>					

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Approved by 	Name <b>[Signature]</b>
Title <b>[Signature]</b>	Position <b>Area Production Supt.</b>
Date	Company <b>Gulf Oil Corporation</b>