| × ,  |   | Form (3+303<br>(Revised 3-55)   |
|--|---|---|
| NEW MEXICO OIL CONSER  | VATION COMMISSION   |   |
| MISCELLANEOUS RE   | í v   | •   |
| (Submit to appropriate District Office   | as per Commission R   | ule H06   |
| COMPANY Gulf Oil Corporation - Box   | 2167. Hobbs. N. H.  |   |
| (Addr  | ·····   |   |
| · · · ·  | ,   |   |
| LEASE <u>Eubank</u> WELL NO.   | 7 UNIT B S 22   | T 21-S R 37-E   |
| DATE WORK PERFORMED Oct. 10 - Nov.   | 1,55POOL Hare   |   |
|  |   | The formation of the off  |
| This is a Report of: (Check appropriate b)   | lock) Results of  | Test of Casing Shut-off   |
| Beginning Drilling Operations  | <b>X</b> Remedial   | Work  |
| Plugging   | Other   |   |
|  |   |   |
| Detailed account of work done, nature and  |   | ised and results obtained.  |
| Perforated additional interval and frac tre  | ated as follows:  |   |
| <ol> <li>Pulled tubing and packer.</li> <li>Cleaned out from 7563-7584' with sa</li> <li>Perforated 7" casing from 7428-7436<br/>jet holes per foot.</li> </ol>  | nd pump. Ran Gamma Kay<br>', 7446-7454' and 7485-   | Neutron Survey.<br>7496' with 4, 1/2"   |
| 4. Set 7" Baker retrievable bride plug<br>perforations in 7" casing from 7535<br>sand per gallon. Avg. inj. rate 9<br>latched onto bridge plug and releas<br>Raised and set parent packer at 738<br>with 5000 gallons Petrogel with 1# | 5-7556' with 5000 gallon<br>bbls per min. Released<br>and same. Reskx's Reset<br>33'. Treated perforatio<br>sand per gallon. Inj. | s Petrogel With 1#<br>parent packer and<br>bridge plug at 7514'.<br>ns from 7428-7496'<br>rate 8.7 bbls per |
| 5. Pulled tubing, bridge plug and pare<br>Sweet hookwall packer at 7335'. Sw<br>load oil.  | ent nacker. Reran 2-3/8   | " tubing set at 7418",<br>ff. Recovered all   |
| FILL IN BELOW FOR REMEDIAL WORK  | REPORTS ONLY  |   |
| Original Well Data:  |   |   |
| DF Elev. 3424' TD 7630' PBD 7534'  | Prod. Int. 7535-7556  | Compl Date <u>9-16-51</u>   |
| Tbng. Dia 2-3/8" Tbng Depth 7506 Oi  | il String Dia <u>7"</u> C   | il String Depth 76291   |
| Perf Interval (s) 7535-7556'   |   |   |
| Open Hole Interval - Produci   | ng Formation (s) Con  | nnell   |
| RESULTS OF WORKOVER:   | BEFOI   | RE AFTER  |
| RESULTS OF WORKOVER.   |   |   |
| Date of Test   | well Dead   | <u>10-1-55</u>  |
| Oil Production, bbls. per day  |   | <u> </u>  |
| Gas Production, Mcf per day  |   | 299   |
| Water Production, bbls. per day  |   | 0   |
| Gas-Oil Ratio, cu. ft. per bbl.  |   | 3440  |
| Gas Well Potential, Mcf per day  |   |   |
| Witnessed by F. J. Jrawford  | Gulf Oil Corp   | pration   |
|  |   | (Company)   |
| OIL CONSERVATION COMMISSION  | I hereby certify that t<br>above is true and com  |   |
| Name ( // Yardy)   | my knowledge.<br>Name   | -Jans   |
| Title  |   | Supt. of Prod.  |
| Date   |   | Dil Corporation   |