

NEW MEXICO OIL CONSERVATION COMMISSION
 MISCELLANEOUS REPORTS ON WELLS

FORM C-103
 (Rev 3-55)

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company The British-American Oil Producing Company		Address Box 474, Midland, Texas				
Lease New Mexico State "P"	Well No. 1	Unit Letter E	Section 4	Township 21-S	Range 35-E	
Date Work Performed 11-8-64	Pool Undesignated			County Lea		

THIS IS A REPORT OF: (Check appropriate block)

Beginning Drilling Operations Casing Test and Cement Job Other (Explain):

Plugging Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

1. Spudded well 4 p.m., 11-7-64
2. Drilled to TD 370' - 17-1/2" hole. Rigged up and ran 13-3/8" OD H-40 ST&C casing. Cemented with 350 sacks regular 2% calcium chloride. Circulated 45 sacks to surface.
3. WOC 18 hrs. Pump tested casing to 1000 psi for 30 minutes. Tested okay.
4. Commenced drilling out cement.

Witnessed by Don Wells	Position Production Engineer	Company The British-American Oil Prod. Co.
----------------------------------	--	--

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY
 ORIGINAL WELL DATA

D F Elev.	TD	PBTD	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	
Perforated Interval(s)				
Open Hole Interval				
Producing Formation(s)				

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Approved by	Name O. O. Flapp
Title	Position District Clerk
Date	Company The British-American Oil Producing Company