

NUMBER OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
TRANSPORTER	OIL
	GAS
PRODUCTION OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company Dalport Oil Corporation				Address 930 Fidelity Union Life Bldg Dallas, Texas			
Lease TP-STATE	Well No. 1	Unit Letter F	Section 17	Township 21S	Range 35E		
Date Work Performed March 25, 1964	Pool Wildcat			County Lea			

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations
 ☒ Casing Test and Cement Job
 ☐ Other (Explain):
☐ Plugging
 ☐ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

Cemented Surface casing

8 joints 8 5/8" J-55 at 258'

W/150 SX Neat cement + 2% calcium chloride

Circulated cement, pressured up to 600#

Tested O. K.

W.C.C. 18/100

Witnessed by Mr. Sutherland	Position Cementer	Company Halliburton Company
------------------------------------	-----------------------------	---------------------------------------

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA

D F Elev.	T D	P B T D	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	
Perforated Interval(s)				
Open Hole Interval		Producing Formation(s)		

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION		I hereby certify that the information given above is true and complete to the best of my knowledge.	
Approved by <i>[Signature]</i>	Name <i>W. E. [Signature]</i>		
Title <i>[Signature]</i>	Position President		
Date <i>[Signature]</i>	Company DALPORT OIL CORPORATION		