

JAKE L. HAMON

OIL PRODUCER

908 VAUGHN BUILDING

MIDLAND, TEXAS

October 10, 1933

Commissioner of Public Lands
Capitol Building
Santa Fe, New Mexico
Attn: Mr. Ray Graham

Re: Jake L. Hamon No. 1
State 1-5521, Lot 12,
Section 4, T-21-S, R-34-E,
Dea County, New Mexico

Gentlemen:

With references to the above captioned well, we wish to submit a daily progress report as follows:

9/16 Drilling at 10,970'
9/17 Trip at 11,020'
9/18 Drilling at 11,061'
9/19 Trip at 11,101'
9/20 Trip at 11,141'
9/21 Trip at 11,182'
9/22 Trip at 11,215'
9/23 Trip at 11,247'
9/24 Drilling at 11,290'
9/25 Drilling at 11,329'
9/26 To 11,350' D.S.T. # 12 from 11,215'-11,350'. Bitum packers failed immediately on opening tool.
9/27 Running D.S.T. #13 from 11,210'-11,350'.
9/28 Drilling at 11,361'. D.S.T. #13, 11210'-11,350', 1/2" B.H.C., 1 hour test. GTS in 12 min. Tested 2 hours on 1/2" surface choke, 70% L.P., 473 M.F.P.P.; 1 hour on 24/64" surface choke, 203% L.P., 161 M.F.P.P.; 1 hour on 16/64" surface choke, 343% L.P., 150 M.F.P.P. Recovered 650' of heavily gas and distillate cut mud. IBIP 2829' in 33 mins., 121 5700, 772 8300, 7512 6720' in 1 hour, INP 7495, PNP 7374. Temp 154° F.

