

JAKE L. HAMON

OIL PRODUCER

908 VAUGHN BUILDING

HOUSTON, TEXAS

HOBBES OFFICE (L.S.)

AUG 14 10 35 AM '64

August 13, 1964

Commissioner of Public Lands
Capitol Building
Santa Fe, New Mexico
Attn: Mr. Ray Graham

Re: Jake L. Hamon No. 1
State N-8321, Lot 12,
Section 4, T-21-S, R-34-E,
Dea County, New Mexico

Gentlemen:

With reference to the above captioned well, we wish to submit a daily progress report as follows:

7/17 Drilling at 4353'
7/18 Making a trip at 4482'
7/19 Drilling at 4690'
7/20 Drilling at 4810'
7/21 Drilling at 4932'
7/22 T.D. 4988'. Fishing for cone
7/23 Drilling at 5110'
7/24 T.D. 5293'. Drill pipe stuck at 3900'
7/25 T.D. 5293'. Drill pipe stuck at 3900'
7/26 T.D. 5293'. Drill pipe stuck at 3932'
7/27 T.D. 5293'. Fishing
7/28 T.D. 5293'. Fishing
7/29 T.D. 5293'. Recovered fish. Cleaning at 2500'
7/30 T.D. 5293'. Running 9 5/8" casing
7/31 T.D. 5293'. Set 9 5/8" casing at 5296' KB. Cemented with 500 sacks cement. Plug down at 1:30 P.M. 7/30/64. Top of cement by temperature survey at 3750' KB. OK.
8/1 T.D. 5293'. Cut off and nipple up. OK
8/2 Making a trip at 5770'. Tested 9 5/8" casing with 2000 psi for 30 minutes, held O.K.
8/3 Drilling at 6350'
8/4 Drilling at 6880'
8/5 Making a trip at 7374'
8/6 Making a trip at 7782'
8/7 T.D. 7782'. Ran DST #1 7500-7782'. Dis-run, packers failed.
8/8 Drilling at 7892'. Ran DST #2 7500-7782'. 5/8" x 5/8" chokes. 1 hour test. Good blow thruout. Recovered: 390' slightly salt water cut mud, 560' mud cut salt water, and 4300' salt water. ISIP 2975#/30 minutes, IFF 472, PFF 2359#, PSIP 2805#/30 minutes.

[illegible][illegible]

1. *Chlorophyll a* (Chl *a*)

...and the fact that the *Journal* is a journal of the American Psychological Association, the largest and most influential organization in the field of psychology, adds to the journal's prestige and makes it a must-read for all psychologists.

...the ...
...the ...
...the ...
...the ...

10