

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator Hanson Oil Corporation		8. Farm or Lease Name Moore
3. Address of Operator P. O. Box 1515, Roswell, New Mexico 88201		9. Well No. 1
4. Location of Well UNIT LETTER I , 1980 FEET FROM THE South LINE AND 410 FEET FROM THE East LINE, SECTION 25 TOWNSHIP 21-S RANGE 36-E NMPM.		10. Field and Pool, or Wildcat Undesignated
15. Elevation (Show whether DF, RT, GR, etc.) 3524' GL, 3534' KB		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-22-70 Total Depth 6000' lime. Ran 192 joints 5 1/2", 15 1/2#, K-55, LT&C casing @ 6000' and cemented with 450 sx. Class C with 3# salt + 1/4# Flocele per sack.

7-23-70 Total Depth 6000' lime. Casing tested with 1000# for 24 hours with no leaks. Temperature survey indicates cement at 3030'.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Gerald E. Harrington TITLE Geologist DATE July 24, 1970

APPROVED BY [Signature] TITLE SUPERVISOR DATE July 24, 1970

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JUL 17 1970

OIL CONSERVATION COMMISSION
HOUSTON, TEXAS