

INCLINATION REPORT

OPERATOR Millard Deck ADDRESS P. O. Box 1047, Eunice, N.M. 88231
 LEASE State WELL NO. 2 FIELD _____
 LOCATION Section 2, T-21-S, R-35-E, Lea County, New Mexico

Depth	Angle Inclination (degrees)	Displacement	Displacement Accumulated
315	1/4	1.3860	1.3860
815	1/2	4.3500	5.7360
1000	1/2	1.6095	7.3455
1400	1/2	3.4800	10.8255
1800	3/4	5.2400	16.0655
2290	3/4	6.4190	22.4845
2766	1 1/4	10.3768	32.8613
3260	2	17.2406	50.1019
3500	2 1/4	9.4320	59.5339
3800	3	15.6900	75.2239
4000	2	6.9800	82.2039

I hereby certify that the above data as set forth is true and correct to the best of my knowledge and belief.

Cactus Drilling Company

Ken Hedrick
 Title: Drilling Superintendent

Affidavit:

Before me, the undersigned authority, appeared Ken Hedrick known to me to be the person whose name is subscribed herebelow, who, on making deposition, under oath states that he is acting for and in behalf of the operator of the well identified above, and that to the best of his knowledge and belief such well was not intentionally deviated from the true vertical whatsoever.

Ken Hedrick
 (Affiant's Signature)

Sworn and subscribed to in my presence on this the 20th day of _____

June 19 72.

RECEIVED

JUL 17 1972

OIL CONSERVATION COMM.
HOBBES, N. M.