

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions
reverse side)

Form approved.
Budget Bureau No. 42-R1424.
LEASE DENOMINATION AND SERIAL NO.

NM - 14329

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different depth.
Use "APPLICATION FOR PERMIT—" for such proposals.)

WELL ☐ GAS ☒ OTHER ☐

NAME OF OPERATOR

Franks Petroleum Inc.

ADDRESS OF OPERATOR

P. O. Box 7665, Shreveport, LA 71107

LOCATION OF WELL (Report location clearly and in accordance with any State requirements.)

See also space 17 below.
At surface

660' FNL & 660' FEL of Section 9-T21S-R32E

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. JOINT AGREEMENT NAME

Union Federal

8. FARM OR LEASE NAME

Union Federal

CCTG.

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Hat Mesa Morrow

11. SEC., T., R., M., OR S.W., AND
SURVEY OR AREA

Section 9-T21S-R32E

12. COUNTY OR PARISH

Lea

13. STATE

New Mexico

1. PERMIT NO.

15. ELEVATIONS (Show whether SP, ST, GR, etc.)

3739 GR

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHUT-IN OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other) 5 1/2" Production Casing

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

7. DESCRIBE PREPARED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Drilled 7 7/8" hole to 14,385'. Set 353 jts. of 5 1/2" 17# S-95 and N-80 Buttress casing to 14,385'. Cemented with 400 sx 50/50 Poz with additives plus 180 sx Class "H" with additives. Waiting on cement 12 hrs. Tested casing to 1500#, held for 30 minutes. Test OK. Moved in Schlumberger to run logs. Ran GR-N from 14,340 to 12,600'. Ran CBL from 14,340', Top of cement 13,502'.

RECEIVED
JAN 27 1982
GEOLOGICAL SURVEY
DAVIS, NEW MEXICO

1. I hereby certify that the foregoing is true and correct.

SIGNED W. L. Chapman TITLE Production Clerk

DATE 1/18/82

(This space for Federal or State office use)

FEB 2 1982

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

U.S. GEOLOGICAL SURVEY
ROSWEIL, NEW MEXICO

*See Instructions on Reverse Side