STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT OIL CONSERVATION DIVISION ---------DISTRIBUTION P. O. BOX 2088 Form C-103 -Revised 10-1-78 JANTA FE SANTA FE, NEW MEXICO 87501 PILE Sa. Indicate Type of Lease U.S.O.S. State [X] LAND OFFICE Fee OPERATOR 5, State Oil & Gas Lease No. V-1902 i. 7. Unit Agreement Name •11. WELL X weit 🖵 ..... 2. Name of Operator 8. Farm or Lease Hame Happy Oil Co./Ghilkat Inc. Chilkat State 6 J. Address of Operator 9. Well No. P. O. Box 343 Artesia, NM 88210 1 4. Location of Well 10, Field and Pool, or Wildcat 330' W S 1650' WHIT LETTER <u>Wilson Yates</u> Seven Rivers 35E 6 21S TOWNSHIP 15. Elevation (Show whether DF, RT, GR, etc.) 12. County Lea Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: ORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ARILY ABANDON COMMENCE DRILLING OPHS PULL OR ALTER CARING HANGE PLANS CASING TEST AND CEMENT JOB 

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

On June 9, 1987 we re-entered the Chilkat State 6 #1 well to evaluate the two upper zones at 3734-44 and 3785-90'. In order to evaluate each zone independently, we set a plug at 3800' and a packer at 3747'. This isolated zone 3785-90 for proper testing. We swabbed the zone dry in about four runs with a show of oil. This was a good indication that this zone had not been opened We continued to swab and had a fluid entry of about properly. 12-15 bbls per day and about 3% oil cut. We shut the well in for about 24 hours. Swabbed back with about the same results. On 6-11-87 we pressure tested the plug, packer and tubing to 3,000 psi, spotted 500 gal acid and propped the zone open with 5,000# of 20-40 sand and 250 bbls of Gel, in addition to the pad and flush We shut the well in overnight. June 12, 1987 we used. circulated the sand out of the hole and swabbed back with a good show of oil and gas. Had a fluid entry of about 65 bbls per day. We continued to swab back until the fluid had cleaned up and installed pump back in hole. Zone 3734-44 will be looked at, at another time.

18. I hereby certify that the information above is true and	complete to the best of my	Anowledge and belief.	- -	
sicuro Alana Manh	Off	ice Manager	DATE 06-2	6-87
CONDITIONS OF APPROVAL, IF ANYI	VITLE		0ATE	30

