

WELL TEST INTERPRETAT		REPORT #:123834	PAGE: 2,
CLIENT : Santa Fe Energy			19-DEC-91
REGION :W.T.D.	SEQUENCE OF EVENTS		FIELD:
DISTRICT:Midland			ZONE :
BASE :Hobbs			WELL :Silbrey 28-1
ENGINEER:Scott			LOCATION:

DATE	TIME (HR:MIN)	DESCRIPTION	ET (MINS)	BHP (PSIA)	WHP (PSIG)
=====					
12-DEC	13:09	Gradient Stop: lube	0	4830	4830
	13:57	Gradient Stop: 10000'	48	5992	
	14:17	Gradient Stop: 12000'	68	6224	
	14:33	Gradient Stop: 13000'	84	6326	
	14:52	Gradient Stop: 13700'	103	6403	
	15:00	Start Flow, begin 4-Point on 9/64" Choke	111	6403	4830
	16:29	Changed Choke To 12/64"	200		4730
	18:08	Changed Choke To 17/64"	299		4668
	18:45	Changed Choke To 16/64"	336		4485
	20:17	Changed Choke To 18/64"	428		4400
	21:35	END FLOW	506	6114	4227
	22:13	Gradient Stop: lube	544	4705	4704