

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPlicate
(Other instructions
verse side)

Budget Bureau No. 1004-1
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL

NM-64602

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Lincoln Federal Unit

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Undes. Bilbrey Morrow Gas

11. SEC., T., R., M., OR BLE. AND
SURVEY OR AREA

Sec. 26, T-21-S, R-32-E

12. COUNTY OR PARISH 13. STATE

Lea

N.M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Collins & Ware, Inc.

3. ADDRESS OF OPERATOR

600 W. Illinois, Suite 701, Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

1980' FSL and 660' FWL of Section 26

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GK, etc.)

3709.8' GL

16

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANT

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details and give pertinent dates, including estimated date of starting and proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

4/21/91: Drilling at 5330'. Formation dolomite and sand. Deviation survey at 4825' 1°
at 5245' 1°
4/22/91: Drilling at 6158'. Formation dolomite and sand. Deviation survey at 5664' 1°
at 6080' 3/4°
4/23/91: Drilling at 7092'. Formation sand and shale. Deviation survey at 6490' 3/4°
at 6901' 1/2°
4/24/91: Drilling at 7805'. Formation sand and shale. Deviation survey at 7311' 3/4°
at 7721' 1/2°
4/25/91: Drilling at 8490'. Formation 90% lime and 10% shale. Deviation survey at
8098' 3/4°
4/26/91: Drilling at 8935'. Formation 90% lime, 10% shale. Deviation survey at
8443' 3/4° at 8616' 1°

18. I hereby certify that the foregoing is true and correct

SIGNED

Sherry L. Jones

TITLE

Agent

DATE

4/30/91

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side