

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. BOX 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-34436
5. Indicate Type of Lease <input type="checkbox"/> STATE <input checked="" type="checkbox"/> FEE
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name NEDU
8. Well No. 515
9. Pool name or Wildcat Eunice; Blinbry-Tubb-Drinkard North
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3447' GR

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator APACHE CORPORATION	
3. Address of Operator 2000 POST OAK BLVD., SUITE 100, HOUSTON, TX 77056-4400	
4. Well Location Unit Letter O : 1131 Feet From The South Line and 1342 Feet From The East Line Section 10 Township 21S Range 37E NMPM Lea County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3447' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO: <input type="checkbox"/> Perform Remedial Work <input type="checkbox"/> Temporarily Abandon <input type="checkbox"/> Plug or Alter Casing <input type="checkbox"/> Other	SUBSEQUENT REPORT OF: <input type="checkbox"/> Remedial Work <input checked="" type="checkbox"/> Commence Drilling Operations <input type="checkbox"/> Casing Test and Cement Job <input checked="" type="checkbox"/> Other-Surf & Prod. Csg.

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work)
SEE RULE 1103.

7/27/98 Spud well @ 3:30 p.m.

7/28/98 Drld. 11" hole to 1310'. Ran 33 jts. 8-5/8", 24# J-55, ST&C csg. Cmt'd w/ 410 sxs PBCZ.
Circ. 96 sxs to pit.

8/10/98 Drld. 7-7/8" hole to 6800'. Ran 154 jts. 5-1/2", 17# J-55, LT&C csg. Cmt'd w/ 950 sxs Interfill "C" and 415 sxs 50/50 POZ. Did not circulate cement. Plug down @ 6:30 a.m.
Top of float collar @ 6707' and top of float shoe @ 6798'. Plug displaced w/ 2% KCL.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE <i>Deborah K. Howard</i>	TITLE Engineering Technician	DATE 8/24/98
TYPE OR PRINT NAME Deborah K. Howard		TELEPHONE NO. 713/296-7152

(This space for State Use)

APPROVED BY <i>[Signature]</i>	TITLE ORIGINAL SIGNED BY	DATE SEP 28 1998
-----------------------------------	-----------------------------	---------------------

CONDITIONS OF APPROVAL, IF ANY:

DATE MARK
FIELD "EP"