

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO.
30-025-34590

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name
PRAIRIE FIRE STATE

8. Well No.

1

9. Pool name or Wildcat
OSUDO WEST (MORROW) #82240

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	
2. Name of Operator Phillips Petroleum Company	
3. Address of Operator 4001 Penbrook Street Odessa, TX 79762	
4. Well Location Unit Letter 7 : 1980 Feet From The NORTH Line and 1650 Feet From The EAST Line Section 2 Township 21-S Range 34-E NMPM LEA County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3710' G.L., 3733' K.B.	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☒ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

05/27/99 Circ. out carbide-drill 11201-11282'.
05/28/99 Drill 11282-11365'.
05/29/99 Drill 11365-11479'.
05/30/99 Drill 11479-11560'. Displaced Aphron mud w/10.0 ppg brine wtr, ROP increased F/5 to 7 FPH to 15-18 FPH.
05/31/99 Drill 11560-11722'. Installed new rotating head and drive bushing. Drill 11722-11857, POOH due to cracked tool jt. box on swivel.
06/01/99 Change-out swivel/TIH to csg seat/change o-ring in swivel/finish TIH (no fill)/drill & survey 11857-11983'.
06/02/99 Drill 11983-12112'. Lost pump press (hole in DP)/pump soft line/POOH (chain out)/LD jt w/hole (std #107 + double)/TIH/circ & cond hole-mud.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Larry M. Sanders TITLE SUPV., REGULATION/PRORATION DATE 06/08/99

TYPE OR PRINT NAME Larry M. Sanders

TELEPHONE NO. (915) 368-1488

(This space for State Use)

APPROVED BY JOHN W. WILLIAMS TITLE SUPV., REGULATION/PRORATION DATE 06/08/99

CONDITIONS OF APPROVAL, IF ANY: