



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office _____
Lease No. **LC - 068085**
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

November 16, _____, **1961**

Well No. ¹_____ is located **1969** ft. from $\begin{Bmatrix} N \\ S \end{Bmatrix}$ line and **660** ft. from $\begin{Bmatrix} E \\ W \end{Bmatrix}$ line of sec **3**
S. E. 1/4 N. E. 1/4 Sec. 3 **23-S** **32-E** **N. M. P. M.**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wildcat **Lea** **New Mexico**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Set 8 5/8" O. D. 24# J-55 8mls. Casing cemented w/75 sacks cement circulated. W.O.C. 7 days 30 min. casing test before and after drlg. plugged w/600# Test O. K.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **O. B. Kiel, Jr.**

Address **Robertson Building**

Wichita Falls, Texas

By _____

Title **Owner**