Form	9-881 8
(Feb	. 1951)

x	

(SUBMIT IN TRIPLICATE)

UNITED STATES

GEOLOGICAL SURVEY

DEPARTMENT OF THE INTERIOR

Land Office	Las	Crue	3
Lease No	0688	48	
Jnit	N		

	SUNDRY N	IOTICES AN	D REPORT	S ON WELLS	
NOT	ICE OF INTENTION TO DRILL		SUBSEQUENT REPORT	OF WATER SHUT-OFF.	
NOT	ICE OF INTENTION TO CHANGE PLAN	ıs	SUBSEQUENT REPORT	OF SHOOTING OR ACIDIZING	
NOT	ICE OF INTENTION TO TEST WATER	SHUT-OFF	SUBSEQUENT REPORT	OF ALTERING CASING	
NOT	ICE OF INTENTION TO RE-DRILL OR	REPAIR WELL	SUBSEQUENT REPORT	OF RE-DRILLING OR REPAIR	
NOT	ICE OF INTENTION TO SHOOT OR AC	IDIZE	SUBSEQUENT REPORT	OF ABANDONMENT	
	ICE OF INTENTION TO PULL OR ALM	****	SUPPLEMENTARY WELL	L HISTORY	
NOT	ICE OF INTENTION TO ABANDON WE	LL			
	(INDICATE	ABOVE BY CHECK MARK NA	TURE OF REPORT, NOTICE	, OR OTHER DATA)	
			December 12	2, 1961	, 19
Well	Marshall No is located	660 ft. from	S line and 1910	ft. from W line of sec	. 19
	Sec. and Sec. No.	235 (Iwp.) 33	nge) (M	eridian)	
C.m	(Field)	(County or Su	bdivision)	New Mexico (State or Territory)	
The e	elevation of the derrick flo				
/P			OF WORK		
(State r	names of and expected depths to ob	jective sands; show sizes, v ing points, and all other	reights, and lengths of pr important proposed wo	roposed casings; indicate mudding jork)	obs, coment-
connerci	ll was drilled to lal quantities en and Laterolog.	a TD of 5322 countered.	' with no o Cored 5124-7	il, gas or water 4', showed no oil	of L. Ran
75 sx ce from 340 plugs w/ a 4" mar	pse to plug and a ment at 10, spot 0-400', spot 5 ax '10#/gal mud; resi ker extending 4'	100°cment cement at si tore location	from 1350-14 arfece and f a to origina	50', spot 15 sx (ill intervals bet 1 condition and (tement Lween Construct
	rbel approval ob				
I un	nderstand that this plan of work mu	st receive approval in writ	ing by the Geological Su	rvey before operations may be comm	nenced.
Comp	oany Continental	Oil Company			**********
Addre	ess Box 68				
	Eunice, New	exi-co	Ву		
0/2 8848	- K4026-2 4M		Title Di	strict Superinter	id ent