

APPROVED

Form 9-221a
(Feb. 1961)

JUL 29 1960

Budget Bureau No. 6-1000
Approval expires 12-31-60

0	

DISTRICT ENGINEER

(SUBMIT IN TRIPLICATE)

Land Office **New Mexico**

Lease No. **0478A**

Unit

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	X
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Ann Davis
Well No. 1 is located 660 ft. from [N] line and 1983 ft. from [E] line of sec. 14
NE 1/4 Sec. 14 235 35E N.M.P.
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wildcat Lea New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

T.D. 4203, 8 5/8 com 325' W/125 sx

Plugged with cement: 3950' to 4050', 1784' to 1880', 830' to 900', 236' to 300'

10' surface cement plug with U.S.G.S. Marker

Cleaned up location

*Inspected 7-18-60
OK for abandonment.
J. J. G.*

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Fred A. Davis**
Address **Box 5093**
Midland, Texas

United States Fidelity & Guaranty Co.

By *[Signature]*
M. J. Baden

Adjuster-in-Charge