

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Water Injection	7. Unit Agreement Name South Eunice (Seven Rivers, Queen) Unit
2. Name of Operator Marathon Oil Company	8. Form of Lease Name Same
3. Address of Operator P.O. Box 2409 Hobbs, New Mexico 88240	9. Well No. 605
4. Location of Well UNIT LETTER <u>K</u> <u>1980</u> FEET FROM THE <u>S</u> LINE AND <u>1980</u> FEET FROM THE <u>W</u> LINE, SECTION <u>25</u> TOWNSHIP <u>22S</u> RANGE <u>36E</u> N.M.P.M.	10. Field and Pool, or Wildcat South Eunice (Seven Rivers, Queen)
15. Elevation (Show whether DE, RT, GR, etc.) GL 3444'; KDB 3455'	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOBS <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Pipe casing bradenhead to surface
PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Dug well cellar out to expose casing bradenhead outlet.

Installed 1" piping from 2" valve on outlet on bradenhead to a point above ground level.
Installed 1" valve on upper end of piping.

Ran bradenhead pressure. Survey indicated no leak.

Piping arrangement, open position of 2" valve and closed position of 1" valve, inspected and approved by New Mexico Oil Conservation Commission Deputy Oil and Gas Inspector, A. A. Plattsmier.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED <u>White Greenough</u>	TITLE <u>Engineer Technician</u>	DATE <u>August 28, 1980</u>
APPROVED BY <u>A. A. Plattsmier</u>	TITLE <u>OIL & GAS INSPECTOR</u>	DATE <u>SEP 1 1980</u>
CONDITIONS OF APPROVAL, IF ANY:		