

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease  
State ☐ Fee ☒

5. State Oil & Gas Lease No.

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Water Injection	7. Unit Agreement Name South Eunice (Seven Rivers, Queen) Unit
2. Name of Operator Marathon Oil Company	8. Form or Lease Name Same
3. Address of Operator P.O. Box 2409 Hobbs, New Mexico 88240	9. Well No. 202
4. Location of Well UNIT LETTER <u>E</u> <u>660</u> FEET FROM THE <u>West</u> LINE AND <u>1980</u> FEET FROM THE <u>North</u> LINE, SECTION <u>26</u> TOWNSHIP <u>22S</u> RANGE <u>36E</u> NMPM.	10. Field and Pool, or Wildcat South Eunice (Seven Rivers, Queen)
15. Elevation (Show whether DF, RT, GR, etc.) DF 3506'; GL 3498'	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOBS <input type="checkbox"/> OTHER <u>Pipe casing bradenhead to surface.</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

Dug well cellar out to expose casing bradenhead outlet.

Installed 1" piping from 2" valve on outlet on bradenhead to a point above ground level.  
Installed 1" valve on upper end of piping.

Ran bradenhead pressure. Survey indicated no leak.

Piping arrangement, open position of 2" valve and closed position of 1" valve, inspected and approved by New Mexico Oil Conservation Commission Deputy Oil and Gas Inspector, A.A. Plattsmier.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Mike Greenough</u>	TITLE <u>Engineer Technician</u>	DATE <u>August 28, 1980</u>
APPROVED BY <u>A.A. Plattsmier</u>	TITLE <u>OIL &amp; GAS INSPECTOR</u>	DATE <u>SEP 1 1980</u>
CONDITIONS OF APPROVAL, IF ANY:		