Energy, M. Als and Natural Resources Department	Form C-103 Revised 1-1-89
submit 3 Copies to Appropriate District Office OIL CONSERVATION DIVISION	WELL API NO.
	30-025-09056
DISTRICT I P.O. Box 1980, Hobbs, NM 88240 Santa Fe, New Mexico 87504-2008	5. Indicate Type of Lease
<u>DISTRICT II</u>	STATE FEE
P.O. Drawer DD, Artesia, NM 88210	6. State Oil & Gas Lease No.
<u>DISTRICT III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR DEEPEN OR PLUG BACK TO A	7. Loase Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"	
(FORM C-101) FOR SUCH PROPOSALS)	Seven Rivers Queen Unit
. Type of Well: OIL GAS The Interview	
WELL Other Injection	8. Well No.
Name of Operator	15
ARCO OIL and GAS COMPANY	9. Pool Name or Wildcat
P.O. Box 1610, Midland, Texas 79702	Eunice SRQ South
Well Locartion	
Unit Letter <u>0</u> : <u>660</u> Feet From The <u>South</u> Line and <u>19</u>	980_Feet from The <u>East</u> L
Section Z/ Township ZZS Thange Sold	MPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, et a 3509 GR	
Check Appropriate Box To Indicate Nature of Notice, Re	eport, or Other Data
NOTICE OF INTENTION TO: S	UBSEQUENT REPORT OF:
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING O	PNS PLUG AND ABANDONMENT
PULL OR ALTER CASING	
1	

Propose to fish CA, repair casing return to injection

18. I hereby certify that the	information above is the	ue and complete to the	best of my	knowledge and belief			
SKENATURE Ken Gr			TITLE .	Demulatery Coordinator	ATE _	1/29/91	
TYPE OR PRINT NAME	Ken W. Gosnell		<u></u>	TBLBPHO	NB	(915) 688-5672	
(This space for State)							
		a an ann an State				• 、	
APPROVED BY CONDITIONS FOR APPROVAL	, IF ANY:		TITLB _			DATE	

WORKOVER PROCEDURE

 ~ 2

DATE: 1/7/91

WELL & JOB	SRQU # 15		DRILLED: 1956					
LAST WORK	OVER: 1984		FIDI	D: 7R Queen	COUNTY: Lea/NM			
BY: GORE		TD: 3814'	PBD):	DATUM: RKB = 13'			
TUBINGHEA	GHEAD: SIZE:			PRESS RATING:				
CASING: SURFACE:	<u>SIZE</u> 8-5/8"	<u>WEIGHT</u> 24#	<u>GRADE</u> J-55	<u>SET @</u> 297'	<u>SX CMT</u> 245	<u>TOC</u> SURFACE		
INTER: PROD:	5-1/2"	14# FG	K-55	3814' 3427'-3808'	1 625	surface 1979		
LINER:	3-1/2"	ГU		5427 5000				

TUBING: Tubing has been pulled. AD-1 packer, 1 jt 2-1/16", & cup type packer left in hole PERFORATIONS: 3690'-3798' SCOPE OF WORK: Repair Casing, Fish CA and return to injection.

PROCEDURE

1. MIRU PU. NU BOPE.

- 2. TIH w/ 4-3/4" bit. Clean out fill in 5-1/2" casing. Production indicates there is fill @ 508' in the well. Production attempted to pull the CA but did not recover the 2 packers as per the attached drawing. The left hand thread on the top sub of the packer was retrieved.
 - a. Square thread looking up
- 3. Fish and recover packer assemblies.
- 4. TIH w/ RBP and packer. Set RBP @ 3400'. Isolate holes in 5-1/2" casing. Squeeze same as per rates and pressures encountered.
- 5. Drill out and test squeeze to 500 psi.
- 6. Rerun CA as before.

M. W. Gore

Concur: R. D. Reynolds J. E. Shields

SRQU # 15 Repair Casing

