



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Las CrucesLease No. LC 030133-bUnit NMPU

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	Subsequent report of plugback <u>X</u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Meyer B-28 May 24, 1956, 19-56

Well No. 1 is located 2310 ft. from [N] line and 330 ft. from [EX] line of sec. 28  
[S] [W]

NW/4 Sec. 28 22-S 36-E NMPU  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

South Eunice Lea New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3508 ft.

### DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Before Workover: TD Lime 4304', PB 3665', DF 10', Elev 3509'. Pay Yates, Seven Rivers 3061-3665'. Casing point 8 5/8" set at 3061'. Before workover well was shut-in.

Work Done: Measured TD at 3665'. Set 7 sacks cement plug from 3665-3648'. Well recompleted within vertical limits of Jalmat Gas Pool.

After Workover: TD Lime 4304', PB 3648', DF 10', Elev 3508'. Pay Yates, Seven Rivers 3061-3648'. Casing point 8 5/8" set at 3061'. Jalmat Pool (Gas) calculated open flow potential 3070 MCF/D. Deliverability at 450 PSIG is 2075 MCF/D. Deliverability at 250 PSIG is 2900 MCF/D. Deliverability at 150 PSIG is 3010 MCF/D. Estimated daily allowable 330 MCF/D. Probable pipeline conn. El Paso Natural Gas Company. Tested 5-21-56. Workover started 5-2-56, completed 5-21-56.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Continental Oil Company

Address Box 68

Eunice

New Mexico

By [Signature]

Title District Superintendent