Form Approved. Form 9-331 " Budget Bureau No. 42-R1424 Dec. 1973 UNITED STATES 5. LEASE DEPARTMENT OF THE INTERIOR LC 30/33 6. IF INDIAN, ALLOTTEE OR TRIBE NAME **GEOLOGICAL SURVEY** 7. UNIT AGREEMENT NAME SUNDRY NOTICES AND REPORTS ON WELLS NMFU (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.) <u>ਬੜ</u> ੂ 8. FARM OR LEASE NAME South Eunice. 1. oil gas other well well 9. WELL NO. 2. NAME OF OPERATOR 10. FIELD OR WILDCAT NAME Conoco Inc. 3. ADDRESS OF OPERATOR Eurice 7 Rivers HOBBS N.M. 88240 11. SEC., T., R., M., OR BLK. AND SURVEY OR P.O. Box 460 **AREA** 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 1980 FNL &FEL 12. COUNTY OR PARISH 13. STATE AT TOP PROD. INTERVAL: ີ່ດ AT TOTAL DEPTH: 14. API NO. 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA 15. ELEVATIONS (SHOW DF, KDB, AND WD) REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF 5 FRACTURE TREAT SHOOT OR ACIDIZE ं किल (NOTE: Report results of multiple completion or change on Form 9-30.) REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) esq 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* お葉が景 50 I'sg. leak survey was performed on Subject well on 8-20-80, Il Valles being dup up & tagged at surface. Subsurface Safety Valve: Manu. and Type _ 1,00% 24,04% 5,08% 1,00% 1,00% 18. I hereby certify that the foregoing is true and correct TITLE ADMIN. SUPERVISOR DATE

for Federal or State office use)

DATE

cijibba Jaob bi meti of no of ance ret neibni noiteluget autocchura

APPROVED BY

CONDITIONS OF APPROVAL

U.S. GEOLOGICAL SURVEY

ROSWELL, NEW MEXICO Instructions on Reverse Side.