NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-101 (Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

	(3	iubmit to approp	riate Distric	t Office o	us per Com	mission Rui	a 1106)		
Name of Company Continental Oil Company Box 68, Eunice, New Mexico									
Lease	COHOTHAL	ART ATT A	Well No.	Unit Lette		Township		ange	
	Meyer A-29)	1	0	29	2	22-S	36-E	
Date Work Performed 12-4-60 Pool Jalmat (Gas) County Lea									
THIS IS A REPORT OF: (Check appropriate block)									
Beginning Drilling Operations Casing Test and Cement Job Other (Explain):									
Plugging Remedial Work Detailed account of work done, nature and quantity of materials used, and results obtained.									
BEFORE WORKOVER: TD 3719'LM, PB 3450', KE 10', Elev 3519' KB, Csg Pt 7" at 3665', Pay Yates & 7-Rivers 3100-3390', Perfs 3100-92', 3200-26', 3268-3300', 3360-90'. Fl 250 BW, W/230 MCFG in 24 hrs. Daily Allow 176 MCF. WORK DONE: Ran tubing with retrievable BP & Pkr. Straddled 3360-90', Swbd 70 BW in 13 1/2 hrs. Straddled 3268-3300', FL 7 BW in 16 hrs, W/est 200 MCFGPD. Straddled 3100-3226', Tested 12 BW in 12 hrs, W/est 150 MCFGPD. Tested casing from surface to 3075'; Tested 0.K. Set retainer at 3340'. Squeezed perfs 3360-3390' W/90 sx cmt. AFTER WORKOVER: TD, PB, KB, Elev, Csg Pt - Same. Pay Yates & 7-Rivers 3100-3300', Perfs 3100-92', 3200-26', 3268-3300'. W/0 unsuccessful. Well unable to produce into EPNG sales line. Workover started 11-6-60, Comp 12-4-60, Tstd-Well Dead.									
Witnessed by Position					Company Continental Oil Company				
R. A. Carlile Drlg. Foreman Continental Oil Company FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY									
				NAL WEL	L DATA				
D F Elev.			PBTI	PBTD		Producing	Interval		
	3519' KB 3710' Tubing Diameter Tubing Depth			3450† Oil String Dis				Oil String Depth	
Tubing Dismerer				3.3.3.3		7m		36651	
Perforated Interval(s) 3100-80', 3200-20', 3270-3300', 3360-90'									
Open Hole In				Prod	lucing Form	ation(s)			
			62011	<u> </u>	ates & DRKOVER	Seven I	Livers		
			T						
Test	Date of Test	Oil Ptoduction BPD		Production CFPD		Production BPD	GOR Cubic feet/Bb	Gas Veil Potential MCFPD	
Before Workover	4-15-60			230		250		Deliv. 404	
After Workover	Well Dead	1							
OIL CONSERVATION COMMISSION					I hereby certify that the information given above is true and complete to the best of my knowledge.				
Approved by					Name / Lank				
Title					Position District Superintendent				
Date	/	· · · · · · · · · · · · · · · · · · ·	Co	Company Continental Oil Company					