



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Cruces
Lease No. 030132-B
Unit Column "B"
Cities Service Oil Co.

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	X
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....	<u>Subsequent Report of Spudding</u>	X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

January 29, 1957

Well No. 11 is located 1900 ft. from N line and 640 ft. from E line of sec. 30
SE NE 30 22-S 36-E NM PM
(¼ Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Jalisco (Gas) Lee New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 3542 ft. Gr.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

This well was spudded at 2:30 P.M. January 22, 1957. It was drilled to 1520' in anhydrite. Ran 48.8 joints (1502.34') of 8 5/8" CD 24.6 lb J-55 SS Csg. set at 1519'. It was cemented with 625 sacks 90% Diamix with 10 sacks gal plus 300 sacks neat on bottom. Cement circulated. Plug was down at 1:00 P.M. January 26, 1957. Cement was allowed to set 48 hours prior to testing for shut-off. Prior to drilling plug, 1000 pounds pressure was applied during a 30 minute interval with no drop in pressure. After drilling plug, 625 pounds pressure was applied during a 30 minute interval with no drop in pressure. Drilling resumed.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Cities Service Oil Company

Address Box 97

Hobbs, New Mexico

By [Signature]

Title District Superintendent

