

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- P & A		7. Unit Agreement Name
2. Name of Operator Atlantic Richfield Company		8. Farm or Lease Name J.L. Selby
3. Address of Operator P. O. Box 1978, Roswell, New Mexico 88201		9. Well No. 1
4. Location of Well UNIT LETTER <u>F</u> , <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>33</u> TOWNSHIP <u>22-S</u> RANGE <u>36-E</u> NMPM.		10. Field and Pool, or Wildcat Jalmat-Yates Gas
15. Elevation (Show whether DF, RT, GR, etc.) 3484' GR		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well has been plugged & abandoned in the following manner:

Spotted 35 sack Class H cement plug from 3000-3200' (across 7" shoe).
Shot off 7" casing @ 1403' and pulled same. Spotted 40 sack Class H
cement plug, half in & half out of 7" casing. Casing stub @ 1403'.
Spotted 10 sack Class H cement plug in surface pipe from 0-23'.
Erected dry hole marker. Well Plugged & Abandoned 12/26/71.

Your office will be notified when this location is ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>D.D. Litcher</u>	TITLE <u>Dist. Drlg. Supervisor</u>	DATE <u>12-29-71</u>
APPROVED BY <u>Nathan E. Clegg</u>	TITLE <u>Oil & Gas Inspector</u>	DATE <u>12-29-71</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

1971

OIL CONSERVATION COMM.
NOV 1 1971