

			X

**(SUBMIT IN TRIPLICATE)**

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Los Cruces

Lease No. **LC 030133 b**

Unit 470

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....		SUBSEQUENT REPORT OF WATER SHUT-OFF.....	X
NOTICE OF INTENTION TO CHANGE PLANS.....		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....		SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....		SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....		SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

**NY 100-8-33**

January 20 1958

Well No. 7 is located 1980 ft. from N line and 1980 ft. from E line of sec. 33

34/4 Dec. 33

225

268

1992

(1/4 Sec. and Sec. No.)

(Twp.)

(Range)

(Meridian)

## South Lunice

100

## How Much?

(Field)

(County or Subdivision)

(State or Territory)

The elevation of the derrick floor above sea level is \_\_\_\_\_ ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded 1-16-58. Ran 12 joints 8 5/8" OD casing; set at 361' with 300 sacks regular, cement circulated. Plug down 1-16-58. Fifteen minute casing test before drilling plug 800-800%, after drilling plug 800-800%.

**I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.**

Company Continental Oil Company

Address F. O. box 68

**Bunice, New Mexico**

By \_\_\_\_\_

Title **District Superintendent**