

	X		

**(SUBMIT IN TRIPLICATE)**

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Las Cruces  
Lease No. LC 030133 (b)  
Unit NMFU

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	
<b>Subsequent Report of Swab Test &amp; Installing Test Pumping Equipment</b>	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

**Meyer B-33**

October 7, 1958

Well No. 8 is located 660 ft. from S line and 1980 ft. from W line of sec. 33

SW/4 Sec. 33

(1/4 Sec. and Sec. No.)

22 S

(Twp.)

36 E

(Range)

**NMFM**

(Meridian)

## South Eunice

(Field)

Lea

(County or Subdivision)

## New Mexico

(State or Territory)

The elevation of the derrick floor above sea level is 3487 ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

BEFORE WORKOVER - TD 3775' Sand & Dol., DOD 3774', DF 10', Elev 3487' DF.  
Pay Seven Rivers 3650-3736'. Csg Pt 5 1/2" at 3774'. Perfs 3650-60', 3671-83.5',  
3712-18', 3726-36'. Well TSD prior to workover due to water intrusion.

WORK DONE - Ran straddle packers and swab tested individual intervals 3726-36', 3712-18', 3671-83.5', 3650-60'. Ran 2 1/2" Tbg. Tbg set at 3640'. Installed test pumping unit.

AFTER WORKOVER - TD, DOD, Pay, and Perfs., same as before workover. On IP pumped 48 BO, 89 BW, in 8 Hrs, W/96.9 MCFGPD. GOR 673. DOR 144 Bbls. Daily allowable 34 BO. Workover started 9-22-58, completed 10-1-58. Well tested 10-6-58.

**I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.**

Company Continental Oil Company

Address Box 68

**Eunice, New Mexico**

By \_\_\_\_\_

Title District Superintendent