

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY Dalport Oil Corporation, 930 Fidelity Union Life Bldg. Dallas, Texas
(Address)

LEASE Otis L. Jones "C" WELL NO. 1 UNIT I S 34 T 22S R 36E

DATE WORK PERFORMED 7-13-57 POOL South Eunice

This is a Report of: (Check appropriate block) ☒ Results of Test of Casing Shut-off

☐ Beginning Drilling Operations

☐ Remedial Work

☐ Plugging

☐ Other _____

Detailed account of work done, nature and quantity of materials used and results obtained.

Cemented 3736' - 5 1/2" O. D - 11# Seamless Casing with 350 Sacks.

Tested with 1000#s - Test O. K.

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl Date _____

Tbng. Dia _____ Tbng Depth _____ Oil String Dia _____ Oil String Depth _____

Perf Interval (s) _____

Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:

BEFORE

AFTER

Date of Test

Oil Production, bbls. per day

Gas Production, Mcf per day

Water Production, bbls. per day

Gas-Oil Ratio, cu. ft. per bbl.

Gas Well Potential, Mcf per day

Witnessed by _____

(Company)

OIL CONSERVATION COMMISSION

Name

Title

Date

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name

Position

Company

Vice-President

Dalport Oil Corporation