

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. A-2614
7. Unit Agreement Name South Eunice (Seven Rivers, Queen) Unit
8. Form of Lease Name Same
9. Well No. 410
10. Field and Pool, or Wildcat South Eunice (Seven Rivers, Queen)
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER - Water Injection
2. Name of Operator Marathon Oil Company
3. Address of Operator P.O. Box 2409 Hobbs, New Mexico 88240
4. Location of Well UNIT LETTER M 330 FEET FROM THE S LINE AND 330 FEET FROM THE W LINE, SECTION 36 TOWNSHIP 22S RANGE 36E N.M.P.M.
15. Elevation (Show whether DF, RT, GR, etc.) DF 3465'; GL 3455'

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Pipe casing bradenhead to surface

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Dug well cellar out to expose casing bradenhead outlet.

Installed 1" piping from 2" valve on outlet on bradenhead to a point above ground level.
Installed 1" valve on upper end of piping.

Ran bradenhead pressure. Survey indicated no leak.

Piping arrangement, open position of 2" valve and closed position of 1" valve, inspected and approved by New Mexico Oil Conservation Commission Deputy Oil and Gas Inspector, A. A. Plattsmier.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED W. L. Greenough

TITLE Engineer Technician

DATE August 28, 1980

APPROVED BY A. A. Plattsmier

TITLE OIL & GAS INSPECTOR

DATE SEP 1 1980

CONDITIONS OF APPROVAL, IF ANY: