

State "A" A/C 1 #46
Langlie Mattix 7 Rvrs Queen Gryb. Field
Lea County, New Mexico

6. RIH W/ 2"x1-1/2"x12' RHBC ROD PUMP ON 66 "K" GRADE ROD STRING. INSPECT & REPLACE ROD COUPLINGS AS NEEDED W/ INSPECTED FULL SIZE REG. "T" COUPLINGS (AVAILABLE AT HOBBS OFFICE). SPACE OUT AS NEEDED. RLSE RIG.

TEST AT 1.5x54x12.