Submit 3 Copies to Appropriate


State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revisied 1-1-89

District Office

OIL CONSERVATION DIVISION

P.O. Box 2088	
Conto En Nov Marina 97504 2089	3
DISTRICT I Santa Fe, New Mexico 87304-2000 P.O. Box 1980, Hobbs, NM 88240	,
DISTRICT II	API NO. (assigned by OCD on New Wells)
P.O. Drawer Dd, Artesia, NM 88210	30-025-09365
DISTRICT III	Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, Nm 87410	STATE FEEX
TOO NO BIBLOS NA., NEIOS, INIII O I IIO	
	6. State Oil & Gas Lease No.
	014904
SUNDRY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"	
(FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well:	J.F. Janda NCT E
OIL GAS	J.F. Janua NOT L
WELL X OTHER	
2. Name of Operator	8. Well No.
Arch Petroleum, Inc.	3
3. Address of Operator	9. Pool name or Wildcat
10 Desta Drive, Suite 420 E, Midland, TX 79705	Jalmat Gas
4. Well Location Link Letter A 360 Feet From The North Line and	330 Feet From The East Line
Office Control	36E NMPM Lea County
Section 21 Township 23S Range	
3432' GR	
Development Making of Making Deport of Other	ur Data
	QUENT REPORT OF:
Notice of internal terms	- · · · · · · · · · · · · · · · · · · ·
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTER CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS.	PLUG AND ABAN.
PULL OR ALTER CASING CASING TEST AND CMT JO]
<u> </u>	ary Abandonment
UTHER.	
12. Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including	ng
esticated date of starting any proposed work) SEE RULE 1103.	
Deparintion of Work:	
Description of Work:	
1) Set 7" CIBP @ 3000' w/2 sx cement	
1) Set 7" CIBP @ 3000' w/2 sx cement	
2) Procure tested 7" casing to 490 psi for 30 minutes	
2) Presure tested 7" casing to 490 psi for 30 minutes.	
· -	
2) Presure tested 7" casing to 490 psi for 30 minutes. (Chart attached) Test witnessed by Gary Wink.	
2) Presure tested 7" casing to 490 psi for 30 minutes.	
2) Presure tested 7" casing to 490 psi for 30 minutes. (Chart attached) Test witnessed by Gary Wink. (2/13/9) 3) Temporarily abandoned wellbore.	3
2) Presure tested 7" casing to 490 psi for 30 minutes. (Chart attached) Test witnessed by Gary Wink. (2) (3) 79) 3) Temporarily abandoned wellbore.	
2) Presure tested 7" casing to 490 psi for 30 minutes. (Chart attached) Test witnessed by Gary Wink. (2) (3) 79) 3) Temporarily abandoned wellbore.	9-4-2002
2) Presure tested 7" casing to 490 psi for 30 minutes. (Chart attached) Test witnessed by Gary Wink. (2) (3) 79) 3) Temporarily abandoned wellbore.	9-4-2002
2) Presure tested 7" casing to 490 psi for 30 minutes. (Chart attached) Test witnessed by Gary Wink. 2/13/97 3) Temporarily abandoned wellbore. This Approach Abandonbant Copy.	9-4-2002
2) Presure tested 7" casing to 490 psi for 30 minutes. (Chart attached) Test witnessed by Gary Wink. 2/13/97 3) Temporarily abandoned wellbore. This Address: Abandoned: Thereby certify that the information above is true and complete to the best of my knowledge and belief.	
2) Presure tested 7" casing to 490 psi for 30 minutes. (Chart attached) Test witnessed by Gary Wink. 2/13/97 3) Temporarily abandoned wellbore. This Approach Abandonbant Copy.	9-4-2002 DATE: 8/25/97
2) Presure tested 7" casing to 490 psi for 30 minutes. (Chart attached) Test witnessed by Gary Wink. 2/13/97 3) Temporarily abandoned wellbore. This Addressed Abandoned Title Abandoned Title Technical Assistant Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNITURE Addressed TITLE Technical Assistant	DATE: 8/25/97
2) Presure tested 7" casing to 490 psi for 30 minutes. (Chart attached) Test witnessed by Gary Wink. 2/13/97 3) Temporarily abandoned wellbore. This Adams 1 Abandan per to the best of my knowledge and belief. Thereby certify that the information above is true and complete to the best of my knowledge and belief. Thereby certify that the information above is true and complete to the best of my knowledge and belief.	DATE: 8/25/97 TELEPHONE NO. 915-685-1961
2) Presure tested 7" casing to 490 psi for 30 minutes. (Chart attached) Test witnessed by Gary Wink. 2/13/97 3) Temporarily abandoned wellbore. This Adams 1/4 Abandone and belief. Title Technical Assistant Title Technical Assistant	DATE: 8/25/97
2) Presure tested 7" casing to 490 psi for 30 minutes. (Chart attached) Test witnessed by Gary Wink. 2/13/97 3) Temporarily abandoned wellbore. This Adams 1 Abandone is true and complete to the best of my knowledge and belief. SIGNITURE And M. M. Carley. TITLE Technical Assistant	DATE: 8/25/97 TELEPHONE NO. 915-685-1961



Hayler. Wink

100 Ved

8-13-97