

N. M. State AA #5, Unit G; Sec. 22; T-23-S; R-36-W; Garfield County, New Mexico
Humble Oil & Refining Company
P. O. Box 2347
Hobbs, New Mexico

Perforated 2-7/8" casing 3678' - 3700' 7/1 jetted. Placed 100% gravel bridge plug at 3708'. Treated interval 3678' - 3700' with 100% refined oil and 30,000# sand. Placed well on pump for testing. Produced 100% refined oil. Checked and found communication between casing 3678' - 3700' and 3713' - 3721'. Repaired communication channel by cementing with Dowell cement. Reperforated 2-7/8" casing 3678' - 3700' 7/1 jetted. Placed 100% refined oil 30,000# sand. Clean out well to 3729'. Produced 100% refined oil zone 3713' - 3721' and 3729' - 3739'. Placed well on pump. Produced 100% refined oil with lease crude, Ok. Placed well on pump. Produced 100% refined oil.